General Environmental Incident Summary

Incident: 4163 Date/Time Notice: 7/12/2016 1200 DEM Incident No:

Responsible Party: Renaissance Transport Ltd

Date Incident:7/11/2016Time Incident:1500Duration:County:BottineauTwp:161Rng:82Sec:23Qtr:Lat:48.76284Long:-101.27760Method:Interpolation from map

Location Description: From the east junction of 5 + 52, 1 mile east

Submitted By: Ernie Kotyluk Affiliation:

Address: Box 46 site 145 rr 1

City: Brandon State: MB Zip: R7A5Y1

Received By:
Contact Person:

Box 46 site 145 rr 1 Brandon, MB

Distance Nearest Occupied Building: 1000 Feet Release Contained: Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: PG-64-28 asphalt oil

Volume Spilled: 300.00 gallons Ag Related: No

EPA Extremely Hazardous Substance: No Reported to NRC: Unknown

Cause of Incident:

Driver swerved to avoid deer causing the pup to move off the pavement. Since there is no shoulder the pup trailer was pulled into the ditch and separated from the lead trailer. It came to rest with the lid pointing down and product slowly leaking out the relief valve.

Risk Evaluation:

zero risk of any kind

of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

100 percent of the spilled product is removed, zero chance of impact

Action Taken or Planned:

Farden Construction from Kenmare responded within an hour of the incident and promptly had the trailer back on its wheels and delivered it to the asphalt plant where it was originally destined. The next morning (July 12) they excavated the site, removing the hardened asphalt and graded the ditch appropriately when finished.

Wastes Disposal Location: The recovered dirt and asphalt will be recycled at the asphalt plant at

Glenburn.

Agencies Involved: State Highway Patrol

Friday, July 15, 2016 Page 1 of 2

Updates

Date: 7/12/2016 Status: Reviewed - Follow-up Required Author: Souder, Taylor

Updated Volume:

Notes:

Further follow-up needed.

Friday, July 15, 2016 Page 2 of 2